

This page lists the know errors on the gm5x5x5 PCBs. There are no known issues with the bulk order run (white pcbs), the following information is valid **only** for the prototype run (green pcbs).

## **Bulk Order #1 (white pcb, rev 1.0)**

### **#1 Silkscreen error (reported by dioioib)**

**Problem:** The silkscreen has the EEPROM the wrong way around - Pin 1 should be facing IC5.

**Solution:** Stick the EEPROM in the other way around, with the “notch” facing IC5.

## **Prototype Run (green PCBs)**


### **#1 MIDI IO pins**

**Problem:** The MIDI IO pins of the midi sockets (Pin 4 + 5) are switched.

**Solution:** Either (1) use the pin-headers if you use sockets that are not mounted on the pcb or (2) break the traces to pins 4 + 5 of the sockets and solder wires to them or (3) solder the midi sockets on the other side of the pcb.

### **#2 MISSING TRACK**

**Problem:** A track between D2 and R3 is missing.



**Solution:** Bridge the pins.

From:

<http://www.midibox.org/dokuwiki/> - MIDIBOX

Permanent link:

[http://www.midibox.org/dokuwiki/doku.php?id=gm5x5x5\\_errata&rev=1265543070](http://www.midibox.org/dokuwiki/doku.php?id=gm5x5x5_errata&rev=1265543070)

Last update: 2010/02/07 11:44

