

The process of calibrating a meter so that it shows a value of zero (0) when zero is being measured. This process must be done to insure accurate readings during the test session.

From:

<http://wiki.midibox.org/> - **MIDIbox**

Permanent link:

<http://wiki.midibox.org/doku.php?id=zeroing>

Last update: **2006/10/15 10:35**

