

To find midi devices known to cause problems check the [midi_interface_blacklist](#).

Known to work MIDI interface/OS combinations include the following:

| Vendor | Model | OSs | notes |
|--------------------------|-----------------|---|---|
| Emagic | amt8 | Mac OS X 10.5 | |
| | Unitor8 | Mac OS X 10.5 | |
| E-MU | 0404 USB | Windows XP, Windows 7 | |
| | 1616 | Windows XP | |
| ESI | RoMI/O I | | |
| M-AUDIO | FastTrack Ultra | Windows 7 64bit | |
| | MIDISport 2x2 | Windows XP , Windows 7 64bit, Linux | Does not work with MIDI Thru toggled. |
| | UNO | Windows XP 32bit | |
| MBHP_USB_PIC | | Windows XP, Windows Vista, Win7, MacOS 10.5, MacOS 10.6 | |
| MIOS32 based USB devices | | Windows XP, Windows Vista, Win7, MacOS 10.5, MacOS 10.6 | |
| MOTU | FastLane USB | Windows XP, MacOS 10.4 | |
| | midi express XT | Win7 64bit | |
| | UltraLite MKIII | MacOS 10.5, MacOS 10.6 | |
| Novation | 25SL mk2 | Windows 7 64bit | |
| Phonic | FireFly 808 | Win7 | |
| Ploytec | gm5 | Windows XP, Win7, MacOS 10.6, Linux | |
| Soundblaster | Audigy | | Some older driver versions don't work reliable, use the latest one. |
| Steinberg | MIDEX3 | Windows XP | |
| | MIDEX8 | Windows XP | |
| Tascam | US-122L | Win7 | |
| Terratec | MIDI Hubble 2x2 | Win7 | |



When adding to this list, try to keep it sorted alphabetically, please.

From:
<https://www.midibox.org/dokuwiki/> - **MIDIbox**

Permanent link:
https://www.midibox.org/dokuwiki/doku.php?id=midi_interface_whitelist&rev=1380900571

Last update: **2013/10/04 15:29**

