

BLM SCALAR FIX

Based on findbhudda's design: <http://www.midibox.org/dokuwiki/doku.php?id=findbuddha>

DESIGN SOFTWARE USED:

Same as findbhudda :)

KiCAD for PCB/Schematics: http://kicad.sourceforge.net/wiki/Main_Page

KNOWN ISSUES / BUILD SUGGESTIONS:

- blm-scalar.* contain an error. Pins I4-I7 are mirrored. This is easily fixed with a connector modification, and the blm-scalar module seems to work as intended.
- blm-scalar v1.1 attempts to fix this error. Moved connectors J1, J2, Resistor Net 1 and R9 to make room for corrections.

DESIGN FILES:

Original files from findbhudda [findbuddha-shared-wiki-docs-0.1.zip](#)

Corrected blm-scalar v1.1.brd [blm-scalar_v1.1.zip](#)

From:

<https://www.midibox.org/dokuwiki/> - **MIDIbox**

Permanent link:

<https://www.midibox.org/dokuwiki/doku.php?id=peterpressure&rev=1323631127>

Last update: **2011/12/11 19:18**

